

# Rocky Corner

Available options. Some restrictions apply to particular units. Prices and availability subject to change.

<b>Option</b>	<b>Code</b>	<b>On A Unit</b>	<b>On B Unit</b>	<b>On C Unit</b>
North 4 ft overhang	PN4	\$3,760	\$4,807	\$4,807
South half-length porch	PSH8	\$4,327	\$4,518	\$4,451
South full-length porch	PSF8	\$5,679	\$6,747	\$6,796
North half-length porch	PNH8	\$6,660	\$7,646	\$6,787
North full-length porch	PNF8	\$9,441	\$11,292	\$11,292
Window bay	WB	\$4,977	\$9,280	\$8,850
Windows centered on end wall	WND	N/A	\$5,482	\$5,052
Add window on 2nd floor	DSF	N/A	N/A	\$2,730
Windows on bedroom side wall	WNDB	N/A	N/A	\$6,953
Add two loft skylights (roof windows)	LSK	\$4,451	\$4,451	\$4,451
Second floor bathroom skylights	BSK	N/A	\$1,554	\$1,554
South half-length dormer	DSH	\$7,843	\$8,706	\$8,328
South full-length dormer	DSF	\$12,927	\$14,700	\$27,065
North half-length dormer	DNH	N/A	N/A	\$17,628
North bathroom dormer	DNB	N/A	\$5,042	N/A
First floor study (in lieu of one bedroom)	ST	N/A	\$716	\$93
Additional first floor half bath	WC	N/A	\$6,004	\$6,041
Pull-down stair instead of staircase	PDS	\$(1,052)	N/A	N/A
Masonry stove setup (excludes stove)	MS	\$678	\$678	\$678
Infill cathedral ceiling (no dormer)	INF	N/A	N/A	\$6,356