

Rocky Corner

Available options. Some restrictions apply to particular units. Prices and availability subject to change.

Option	Code	On A Unit	On B Unit	On C Unit
North 4 ft overhang	PN4	\$3,686	\$4,713	\$4,713
South half-length porch	PSH8	\$6,217	\$7,253	\$7,098
South full-length porch	PSF8	\$8,878	\$11,083	\$11,116
North half-length porch	PNH8	\$7,950	\$9,718	\$9,596
North full-length porch	PNF8	\$11,617	\$14,950	\$14,950
Window bay	WB	\$7,137	\$10,863	\$10,800
Windows centered on end wall	WND	N/A	\$5,757	\$5,310
Add window on 2nd floor	DSF	N/A	N/A	\$2,908
Windows on bedroom side wall	WNDB	N/A	N/A	\$7,056
Add two loft skylights (roof windows)	LSK	\$4,960	\$4,960	\$4,960
Second floor bathroom skylights	BSK	N/A	\$2,139	\$2,139
South half-length dormer	DSH	\$11,048	\$11,859	\$11,822
South full-length dormer	DSF	\$15,725	\$17,322	\$29,207
North half-length dormer	DNH	N/A	N/A	\$19,591
North bathroom dormer	DNB	N/A	\$6,217	N/A
First floor study (in lieu of one bedroom)	ST	N/A	\$771	\$100
Additional first floor half bath	WC	N/A	\$7,185	\$7,303
Pull-down stair instead of staircase	PDS	\$(1,026)	N/A	N/A
Infill cathedral ceiling (no dormer)	INF	N/A	N/A	\$9,470